

[Effective Immediately](#)

[Is this email not displaying correctly?](#)
[View it in your browser.](#)



Motorcycling New Zealand - Safety Rule Change Appendix H, 9i (Road)

MNZ would like to advise of the following Safety Rule effective immediately:

Appendix H - 9i (New Rule):

Side stand bracket. Care must be taken to not damage the frame rail during the removal process. The approved method is to use a steel cut off blade on an angle grinder.

Please update your Manual of Motorcycle Sport to include this change.